DEKRA

True View Inspection

Report No: 2017324029
Date: 11/11/2026



Assignment

Requested Date:	11/11/2026	**Inspection Location:**	Midrand Midrand Motor City, Old Pretoria Road, UNIT 54BERG - 1685 Midrand - GT
Inspection Date:	11/11/2026		

Vehicle Data

Vehicle Type:	PASSENGER VEHICLE	**Reg No:**	CAA612970
Manufacturer:	MERCEDES -BENZ	**Register No:**	GYK473X
Model:	VITO	**First Licensing:**	
VIN:	W1V44770324438187	**Fuel:**	DIESEL
Engine No:	65492082195867	**Odometer:**	54,386 KM

Exhaust System

Brakes

Axle	Left Braking Force [KN]	Right Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	4.4	4.3	-	
Rear	3.6	3.8	-	
Emergency / Parking	2	2	-	

Tyres

Position	Size	Load/Speed Index	Manufacturer	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/55R17	109H	CONTINENTAL	VANCONTACT	V	1925	5
Front Right	225/55R17	109H	CONTINENTAL	VANCONTACT	V	1925	5
Rear Left	225/55R17	109H	DUNLOP	Econodrive	V	0724	4
Rear Right	225/55R17	109H	DUNLOP	Econodrive	V	0724	4
Spare	225/55R17C	109H	DUNLOP	Econodrive	V	2224	5

Diagnostic

A vehicle diagnostic has not been conducted.
Diagnostic could not be performed due to no data available and or OBD interface malfunction.

Axles & Undercarriage

Electrical Systems

Engine & Transmission

Exterior & Interior

General Photos



1. Front right corner



2. Rear left corner



3. Interior (Front driver door)



4. Dashboard (Taken from the rear seat)



5. Cluster (While engine is running)



6. Odometer



7. License disc



8. VIN plate/sticker



9. Front



10. Right



11. Rear



12. Left



13. Front left tyre tread



14. Rear left tyre tread



15. Rear right tyre tread



16. Front right tyre tread



17. Engine compartment



18. Oil cap and dip stick



19. Expansion bottle/Coolant level



20. Engine bottom



21. Chassis front



22. Chassis rear

Inspection Conditions

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

General Comments

ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKINGS ARE VISIBLE ON THE EXTERIOR, INTERIOR, ELECTRICAL, AND MECHANICAL PARTS.

Disclaimer

The DEKRA True View Inspection is a visual and functional check of listed items. Concealed/hidden defects are not covered. DEKRA does not dismantle or strip parts. Road testing is limited. Valid only for the vehicle and condition at inspection time. DEKRA T&Cs apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave, Klerksoord, Pretoria, 0200
Phone: 012 542 4867 | www.dekraauto.co.za

VIN: W1V44770324438187