DEKRA

True View Inspection

Report No: 2017319721
Date: 30/10/2026



Assignment

Requested Date:	30/10/2026	**Inspection Location:**	DEKRA Randburg 114 BORDEAUX DRIVE - 2194 Randburg -
Inspection Date:	30/10/2026		

Vehicle Data

Vehicle Type:	PASSENGER VEHICLE	**Reg No:**	MH44JGGP
Manufacturer:	BMW	**Register No:**	HMC279X
Model:	X1	**First Licensing:**	
VIN:	WBA22EE0X05217628	**Fuel:**	PETROL
Engine No:		**Odometer:**	31,023 KM

Exhaust System

Brakes

Axle	Left Braking Force [KN]	Right Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.4	2.6	-	
Rear	2.3	2.4	-	
Emergency / Parking	2.7	3	-	

Tyres

Position	Size	Load/Speed Index	Manufacturer	Model	Type*	Production Date	Tread Depth (mm)
Front Left	245/45R19	102Y	Bridgestone	Turanza	V	13/26	5
Front Right	245/45R19	102Y	Bridgestone	Turanza	V	11/26	5
Rear Left	245/45R19	102Y	Hankook	Ventus S1	V	48/24	4
Rear Right	245/45R19	102Y	Hankook	Ventus S1	V	48/24	4
Spare	135/80R17	103M	LEAO	Temporary	V	00/00	4

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
2	FLER(FRONTAL LIGHT ELECTRONICS RIGHT)	DA3406	NO MESSAGE (EFFICIENT MODE CONFIGURATION); RECIEVE	0

No	System	Code	Description	Status
3	FZD(ROOF FUNCTION CENTER)	030208	SLIDING/TILT SUNROOF: HALL EFFECT SENSOR A OR B	0

Axles & Undercarriage

Electrical Systems

Engine & Transmission

Exterior & Interior

Inspection Conditions

Engine number not visible without dismantling. Inspection conditions were sufficient.

Engine number â€“ not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

General Comments

ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE. NORMAL WEAR AND TEAR MARKS ON THE INTERIOR; EXTERIOR AND MECHANICAL PARTS.

Disclaimer

The DEKRA True View Inspection is a visual and functional check of listed items. Concealed/hidden defects are not covered. DEKRA does not dismantle or strip parts. Road testing is limited. Valid only for the vehicle and condition at inspection time. DEKRA T&Cs apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave, Klerksoord, Pretoria, 0200
Phone: 012 542 4867 | www.dekraauto.co.za

VIN: WBA22EE0X05217628