DEKRA

True View Inspection

Report No: 2017311381
Date: 13/10/2026









Assignment

Requested Date:	13/10/2026	**Inspection Location:**	DEKRA Ballito Unit 59 Laguna Seca - 4430 DEKRA Ballito -
Inspection Date:	13/10/2026		

Vehicle Data

Vehicle Type:	PASSENGER VEHICLE	**Reg No:**	CAA606625
Manufacturer:	SUZUKI	**Register No:**	GKD927X
Model:	JIMNY 1.5 GLX 5-DR 4X4 AT [2023-ON]	**First Licensing:**	
		Fuel:	PETROL
VIN:	MA3JJC74W00158886	**Odometer:**	49,576 KM
Engine No:			

Exhaust System

Brakes

Axle	Left Braking Force [KN]	Right Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres

Position	Size	Load/Speed Index	Manufacturer	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/80/R15	96s	BRIDGESTONE	DUELER	V	4123	6
Front Right	195/80/R15	96s	BRIDGESTONE	DUELER	V	4223	7
Rear Left	195/80/R15	96s	BRIDGESTONE	DUELER	V	4223	4
Rear Right	195/80/R15	96s	BRIDGESTONE	DUELER	V	4223	4

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufactures).

Axles & Undercarriage

Electrical Systems

Engine & Transmission

Exterior & Interior

Inspection Conditions

Engine number not visible without dismantling. Inspection conditions were sufficient.

Vehicle Dirty

Inspection conditions for the vehicle inspection were sufficient

General Comments

ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE EXTERIOR, INTERIOR, ELECTRICAL, AND MECHANICAL PARTS.

Disclaimer

The DEKRA True View Inspection is a visual and functional check of listed items. Concealed/hidden defects are not covered. DEKRA does not dismantle or strip parts. Road testing is limited. Valid only for the vehicle and condition at inspection time. DEKRA T&Cs apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave, Klerksoord, Pretoria, 0200
Phone: 012 542 4867 | www.dekraauto.co.za

VIN: MA3JJC74W00158886