True View Inspection

Report No: 2017315650
Date: 22/10/2026



Assignment

Requested Date:	22/10/2026	**Inspection Location:**	DEKRA N1 City Cnr Louwtjie Rothman & Manus Gerber - 7463 N1 City - WC
Inspection Date:	22/10/2026		

Vehicle Data

Vehicle Type:	PASSENGER VEHICLE	**Reg No:**	LDD919NW
Manufacturer:	HYUNDAI	**Register No:**	CHG629X
Model:	TUCSON 2.0 115KW EXECUTIVE AT [2018-2022]	**First Licensing:**	
		Fuel:	PETROL
VIN:	TMAJ3813MLJ164085	**Odometer:**	71,401 KM
Engine No:	G4NAKW095083		

Exhaust System

Brakes

Axle	Left Braking Force [KN]	Right Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.4	3.9	-	
Rear	2.1	2.4	-	
Emergency / Parking	1	2.8	-	

Tyres

Position	Size	Load/Speed Index	Manufacturer	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/55R18	102w	HILO	SPORT	V	1826	5
Front Right	225/55R18	102w	HILO	SPORT	V	1826	5
Rear Left	225/55R18	102w	HILO	SPORT	V	1826	5
Rear Right	225/55R18	102w	HILO	SPORT	V	1826	5
Spare	225/55R18	98v	HANKOOK	VENTUS	V	0000	7

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufactures).

Axles & Undercarriage



Steering Box: Right - Loose / Excessive Play.
Repair Way: Roadworthy Relevant
Comment: STEERING NOISY

Electrical Systems

Engine & Transmission

Exterior & Interior



Sun Visor: Right - Broken.
Comment: OBSERVATION

Inspection Conditions

Engine number not visible without dismantling. Inspection conditions were sufficient.

Vehicle Dirty

Engine number â€“ not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

General Comments

ACCORDING TO THE AGE AND MILAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE EXTERIOR AND INTERIOR ELECTRICAL AND MECHANICAL PARTS.

Disclaimer

The DEKRA True View Inspection is a visual and functional check of listed items. Concealed/hidden defects are not covered. DEKRA does not dismantle or strip parts. Road testing is limited. Valid only for the vehicle and condition at inspection time. DEKRA T&Cs apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave, Klerksoord, Pretoria, 0200
Phone: 012 542 4867 | www.dekraauto.co.za

VIN: TMAJ3813MLJ164085