True View Inspection

Report No: 2017308888
Date: 07/10/2026



Assignment

Requested Date:	07/10/2026	**Inspection Location:**	DEKRA EGOLI 103 turffontein road turffontein - 2190 EGOLI - GT
Inspection Date:	07/10/2026		

Vehicle Data

Vehicle Type:	PASSENGER VEHICLE	**Reg No:**	LR98XRGP
Manufacturer:	BMW	**Register No:**	GNL084X
Model:	X3 XLINE XDRIVE20D MHEV DSL SAV STEPTRONIC [2022-2024]	**First Licensing:**	
		Fuel:	DIESEL
VIN:	WBA36BZ0X0N277720	**Odometer:**	47,652 KM
Engine No:	58487303		

Exhaust System

Brakes

Axle	Left Braking Force [KN]	Right Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres

Position	Size	Load/Speed Index	Manufacturer	Model	Type*	Production Date	Tread Depth (mm)
Front Left	245/45R20	103W	Bridgestone	Alenza	V	0826	4
Front Right	245/45R20	103W	Bridgestone	Alenza	V	0926	4
Rear Left	275/40R20	106W	Bridgestone	Alenza	V	0626	5
Rear Right	275/40R20	106W	Bridgestone	Alenza	V	0626	5

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufactures).

Axles & Undercarriage

Electrical Systems

Engine & Transmission

Exterior & Interior

Inspection Conditions

Engine number not visible without dismantling. Inspection conditions were sufficient.

Engine number â€“ not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

General Comments

ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE EXTERIOR, INTERIOR, ELECTRICAL, AND MECHANICAL PARTS.

Disclaimer

The DEKRA True View Inspection is a visual and functional check of listed items. Concealed/hidden defects are not covered. DEKRA does not dismantle or strip parts. Road testing is limited. Valid only for the vehicle and condition at inspection time. DEKRA T&Cs apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave, Klerksoord, Pretoria, 0200
Phone: 012 542 4867 | www.dekraauto.co.za

VIN: WBA36BZ0X0N277720