DEKRA

True View Inspection

Report No: 2017312491
Date: 15/10/2026



Assignment

Requested Date:	15/10/2026	**Inspection Location:**	DEKRA Isando 1 Trek road - 1601 Isando - GT
Inspection Date:	15/10/2026		

Vehicle Data

Vehicle Type:	PASSENGER VEHICLE	**Reg No:**	JX38PWGP
Manufacturer:	BMW	**Register No:**	CLX487X
Model:	X1 SERIES	**First Licensing:**	
VIN:	WBA32AA0995T13768	**Fuel:**	PETROL
Engine No:	37056321	**Odometer:**	117,598 KM

Exhaust System

Brakes

Axle	Left Braking Force [KN]	Right Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.9	3.3	-	
Rear	2.5	2.5	-	
Emergency / Parking	2.4	2.3	-	

Tyres

Position	Size	Load/Speed Index	Manufacturer	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/50R18	95W	HANKOOK	VENTUS	V	4824	7
Front Right	225/50R18	95W	HANKOOK	VENTUS	V	5224	7
Rear Left	225/50R18	95W	HANKOOK	VENTUS	V	5224	7
Rear Right	225/50R18	95W	HANKOOK	VENTUS	V	4824	7
Spare	T135/90R17	104M	HANKOOK	TEMPORARY US	V	1420	7

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Axles & Undercarriage

Electrical Systems

Engine & Transmission

Exterior & Interior

Inspection Conditions

Engine number not visible without dismantling. Inspection conditions were sufficient.

Engine number â€“ not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

General Comments

ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE EXTERIOR, INTERIOR, ELECTRICAL, AND MECHANICAL PARTS.

Disclaimer

The DEKRA True View Inspection is a visual and functional check of listed items. Concealed/hidden defects are not covered. DEKRA does not dismantle or strip parts. Road testing is limited. Valid only for the vehicle and condition at inspection time. DEKRA T&Cs apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave, Klerksoord, Pretoria, 0200
Phone: 012 542 4867 | www.dekraauto.co.za

VIN: WBA32AA0995T13768