True View Inspection

Report No: 2017314184
Date: 19/10/2026



Assignment

Requested Date:	19/10/2026	**Inspection Location:**	DEKRA Randburg 114 BORDEAUX DRIVE - 2194 Randburg - GT
Inspection Date:	19/10/2026		

Vehicle Data

Vehicle Type:	PASSENGER VEHICLE	**Reg No:**	NP2191ZN
Manufacturer:	BMW	**Register No:**	FFC107X
Model:	M240I XDRIVE SPORT COUPE 8-SP STEPTRONIC [2022-ON]	**First Licensing:**	
		Fuel:	PETROL
VIN:	WBA52CM0108C74336	**Odometer:**	30,921 KM
Engine No:	13426776		

Exhaust System

Brakes

Axle	Left Braking Force [KN]	Right Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres

Position	Size	Load/Speed Index	Manufacturer	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/40R19	93Y	Bridgestone	Turanza	V	01/28	4
Front Right	225/40R19	93Y	Bridgestone	Turenza	V	33/25	4
Rear Left	255/35R19	96Y	Bridgestone	Potenza	V	18/24	4
Rear Right	255/35R19	96Y	Bridgestone	Potenza	V	18/24	4

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufactures).

Axles & Undercarriage

Electrical Systems

Engine & Transmission

Exterior & Interior

Inspection Conditions

Engine number not visible without dismantling. Inspection conditions were sufficient.

Engine number â€“ not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Inspection conditions for the vehicle inspection were insufficient

General Comments

ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE EXTERIOR, INTERIOR, ELECTRICAL, AND MECHANICAL PARTS.

Disclaimer

The DEKRA True View Inspection is a visual and functional check of listed items. Concealed/hidden defects are not covered. DEKRA does not dismantle or strip parts. Road testing is limited. Valid only for the vehicle and condition at inspection time. DEKRA T&Cs apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave, Klerksoord, Pretoria, 0200
Phone: 012 542 4867 | www.dekraauto.co.za

VIN: WBA52CM0108C74336