DEKRA

True View Inspection

Report No: 2017314629
Date: 20/10/2026








Assignment

Requested Date:	20/10/2026	**Inspection Location:**	DEKRA EGOLI 103 turffontein road turffontein - 2190 EGOLI - GT
Inspection Date:	20/10/2026		

Vehicle Data

Vehicle Type:	PASSENGER VEHICLE	**Reg No:**	MG37WZGP
Manufacturer:	CHERY	**Register No:**	HKD750X
Model:	TIGGO 4 CROSS 1.5 LIT [2026-ON]	**First Licensing:**	
		Fuel:	PETROL
VIN:	LVVDB21B6RC141874	**Odometer:**	24,196 KM
Engine No:			

Exhaust System

Brakes

Axle	Left Braking Force [KN]	Right Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.1	1.98	-	
Rear	1.43	1.41	-	
Emergency / Parking	1.09	1.14	-	

Tyres

Position	Size	Load/Speed Index	Manufacturer	Model	Type*	Production Date	Tread Depth (mm)
Front Left	215/60/17	96H	Chao Yang		V	07/24	6
Front Right	215/60/17	96H	Chao Yang		V	07/24	6
Rear Left	215/60/17	96H	Chao Yang		V	33/24	6
Rear Right	225/60/17	96H	Chao Yang		V	33/24	6
Spare	T125/80/17	99M	Linglong	Temporary		00/00	2

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Axles & Undercarriage

Electrical Systems

Engine & Transmission

Exterior & Interior



Windscreen: Front - Cracked.

Inspection Conditions

Engine number not visible without dismantling. Inspection conditions were sufficient.

Engine number â€“ not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

General Comments

ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE EXTERIOR, INTERIOR, ELECTRICAL, AND MECHANICAL PARTS.

Disclaimer

The DEKRA True View Inspection is a visual and functional check of listed items. Concealed/hidden defects are not covered. DEKRA does not dismantle or strip parts. Road testing is limited. Valid only for the vehicle and condition at inspection time. DEKRA T&Cs apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave, Klerksoord, Pretoria, 0200
Phone: 012 542 4867 | www.dekraauto.co.za

VIN: LVVDB21B6RC141874