DEKRA

True View Inspection

Report No: 2017323035
Date: 09/11/2026









Assignment

Requested Date:	09/11/2026	**Inspection Location:**	277 SOUTHERN KLIPRIVIERBERG RD - 2001 CITY DEEP -
Inspection Date:	09/11/2026		

Vehicle Data

Vehicle Type:	PASSENGER VEHICLE	**Reg No:**	KPF811EC
Manufacturer:	ISUZU	**Register No:**	HSV926X
Model:	MU-X	**First Licensing:**	
VIN:	MPAUCS40GST002050	**Fuel:**	DIESEL
Engine No:		**Odometer:**	32,096 KM

Exhaust System

Brakes

Axle	Left Braking Force [KN]	Right Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres

Position	Size	Load/Speed Index	Manufacturer	Model	Type*	Production Date	Tread Depth (mm)
Front Left	265/50R20	111H	Dunlop	Grand trek	V	4925	5
Front Right	265/50R20	111H	Dunlop	Grand trek	V	4925	5
Rear Left	265/50R20	107S	Bridgestone	Dueler	V	4924	5
Rear Right	265/50R20	107S	Bridgestone	Dueler	V	4924	5
Spare	265/50R20	107S	Bridgestone	Dueler	V	0000	7

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
2	HEADLAMP AUTOMATIC LEVELING	B1037_54	VEHICLE REFERENCE POSITION NOT INITIALIZED	PRESENT

Axles & Undercarriage

Electrical Systems

Engine & Transmission

Exterior & Interior

Inspection Conditions

Vehicle Dirty

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

General Comments

ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE EXTERIOR, INTERIOR, ELECTRICAL, AND MECHANICAL PARTS.

Disclaimer

The DEKRA True View Inspection is a visual and functional check of listed items. Concealed/hidden defects are not covered. DEKRA does not dismantle or strip parts. Road testing is limited. Valid only for the vehicle and condition at inspection time. DEKRA T&Cs apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave, Klerksoord, Pretoria, 0200
Phone: 012 542 4867 | www.dekraauto.co.za

VIN: MPAUCS40GST002050