DEKRA

True View Inspection

Report No: 2017330181
Date: 25/11/2026









Assignment

Requested Date:	25/11/2026	**Inspection Location:**	CITY DEEP 277 SOUTHERNKLIPRIVERSBURG - 2001 CITY DEEP -
Inspection Date:	25/11/2026		

Vehicle Data

Vehicle Type:	PASSENGER VEHICLE	**Reg No:**	KPY618EC
Manufacturer:	ISUZU	**Register No:**	HXG421X
Model:	MU-X 3.0 DDI LS DSL AT [2025-2026]	**First Licensing:**	
		Fuel:	DIESEL
VIN:	MPAUCR40GST001304	**Odometer:**	31,704 KM
Engine No:			

Exhaust System

Brakes

Axle	Left Braking Force [KN]	Right Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.5	3.4	-	
Rear	2.2	2.1	-	
Emergency / Parking	1.9	1.8	-	

Tyres

Position	Size	Load/Speed Index	Manufacturer	Model	Type*	Production Date	Tread Depth (mm)
Front Left	265/60R18	110H	Dunlop	Grandtrek	V	1925	1
Front Right	265/60R18	110H	Dunlop	Grandtrek	V	1925	2
Rear Left	265/60R18	110H	Autogrip	Grip 4000	V	1426	7
Rear Right	265/60R18	110H	Autogrip	Grip4000	V	1426	7
Spare	265/60R18	110H	Dunlop	Grandtrek	V	0000	6

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).


Axles & Undercarriage

Electrical Systems

Engine & Transmission

Exterior & Interior


General Photos



1. Front right corner



2. Rear left corner




3. Interior (Front driver door)




4. Dashboard (Taken from the rear seat)



5. Cluster (While engine is running)



6. Odometer



7. License disc



8. VIN plate/sticker



9. Front



10. Right




11. Rear




12. Left



13. Front left tyre tread



14. Rear left tyre tread




15. Rear right tyre tread



16. Front right tyre tread



17. Engine compartment




18. Oil cap and dip stick



19. Expansion bottle/Coolant level



20. Engine bottom



21. Chassis front



22. Chassis rear

Inspection Conditions

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

General Comments

ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE EXTERIOR, INTERIOR, ELECTRICAL, AND MECHANICAL PARTS.

Disclaimer

The DEKRA True View Inspection is a visual and functional check of listed items. Concealed/hidden defects are not covered. DEKRA does not dismantle or strip parts. Road testing is limited. Valid only for the vehicle and condition at inspection time. DEKRA T&Cs apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave, Klerksoord, Pretoria, 0200
Phone: 012 542 4867 | www.dekraauto.co.za

VIN: MPAUCR40GST001304