DEKRA

True View Inspection

Report No: 2017329006
Date: 23/11/2026



Assignment

Requested Date:	23/11/2026	**Inspection Location:**	277 SOUTHERN KLIPRIVIERBERG RD - 2001 CITY DEEP - GT
Inspection Date:	23/11/2026		

Vehicle Data

Vehicle Type:	PASSENGER VEHICLE	**Reg No:**	KPF747EC
Manufacturer:	ISUZU	**Register No:**	HSV949X
Model:	MU-X	**First Licensing:**	
VIN:	MPAUCR40GST000483	**Fuel:**	DIESEL
Engine No:	4JJ3EZW230	**Odometer:**	33,125 KM

Exhaust System

Brakes

Axle	Left Braking Force [KN]	Right Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	4.4	4.4	-	
Rear	3.6	3.5	-	
Emergency / Parking	4	3.9	-	


Tyres

Position	Size	Load/Speed Index	Manufacturer	Model	Type*	Production Date	Tread Depth (mm)
Front Left	265/60R18	110H	Dunlop	Grand trek	V	5024	0
Front Right	265/60R18	110H	Dunlop	Grand trek	V	5024	2
Rear Left	265/60R18	110H	Dunlop	Grand trek	V	5024	4
Rear Right	265/60R18	110H	Dunlop	Grand trek	V	5024	4
Spare	265/60R18	110H	Dunlop	Grand trek	V	0000	5

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufactures).

Axles & Undercarriage



Alignment: Left Right Front - Incorrect.

Electrical Systems

Engine & Transmission

Exterior & Interior


General Photos



1. Front right corner



2. Rear left corner




3. Interior (Front driver door)



4. Dashboard (Taken from the rear seat)



5. Cluster (While engine is running)



6. Odometer



7. License disc



8. VIN plate/sticker



9. Front



10. Right



11. Rear




12. Left




13. Front left tyre tread



14. Rear left tyre tread




15. Rear right tyre tread



16. Front right tyre tread



17. Engine compartment



18. Oil cap and dip stick



19. Expansion bottle/Coolant level



20. Engine bottom



21. Chassis front



22. Chassis rear

Inspection Conditions

Vehicle Dirty

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

General Comments

ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKINGS ARE VISIBLE ON THE EXTERIOR, INTERIOR, ELECTRICAL, AND MECHANICAL PARTS.

Disclaimer

The DEKRA True View Inspection is a visual and functional check of listed items. Concealed/hidden defects are not covered. DEKRA does not dismantle or strip parts. Road testing is limited. Valid only for the vehicle and condition at inspection time. DEKRA T&Cs apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave, Klerksoord, Pretoria, 0200
Phone: 012 542 4867 | www.dekraauto.co.za

VIN: MPAUCR40GST000483