DEKRA

True View Inspection

Report No: 2017330420
Date: 26/11/2026








Assignment

Requested Date:	26/11/2026	**Inspection Location:**	Midrand Midrand Motor City, Old Pretoria Road, UNIT 54BERG - 1685 DEKRA Midrand - GT
Inspection Date:	26/11/2026		

Vehicle Data

Vehicle Type:	PASSENGER VEHICLE	**Reg No:**	MS19TBGP
Manufacturer:	TOYOTA	**Register No:**	KVK073L
Model:	STARLET	**First Licensing:**	
VIN:	JTDJWCA3S00A56757	**Fuel:**	PETROL
Engine No:	K15BN1612847	**Odometer:**	28,645 KM

Exhaust System

Brakes

Axle	Left Braking Force [KN]	Right Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	1.9	2.0	-	
Rear	1.5	1.6	-	
Emergency / Parking	0.8	1	-	

Tyres

Position	Size	Load/Speed Index	Manufacturer	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/55R16	87H	Apollo	Alnac	V	2125	3
Front Right	195/55R16	87H	Apollo	Alnac	V	2125	3
Rear Left	195/55R16	87H	Apollo	Alnac	V	2125	4
Rear Right	195/55R16	87H	Apollo	Alnac	V	2125	4
Spare	135/70R15	99M	Jk tyre	Temporary	V	1725	3

Diagnostic

A vehicle diagnostic has not been conducted.
Diagnostic could not be performed due to no data available and or OBD interface malfunction.

Axles & Undercarriage

Electrical Systems

Engine & Transmission

Exterior & Interior

General Photos



1. Front right corner



2. Rear left corner



3. Interior (Front driver door)



4. Dashboard (Taken from the rear seat)



5. Cluster (While engine is running)



6. Odometer



7. License disc



8. VIN plate/sticker



9. Front



10. Right



11. Rear



12. Left



13. Front left tyre tread



14. Rear left tyre tread



15. Rear right tyre tread



16. Front right tyre tread



17. Engine compartment



18. Oil cap and dip stick



19. Expansion bottle/Coolant level



20. Engine bottom



21. Chassis front



22. Chassis rear

Inspection Conditions

Inspection conditions for the vehicle inspection were sufficient

General Comments

ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKINGS ARE VISIBLE ON THE EXTERIOR, INTERIOR, ELECTRICAL, AND MECHANICAL PARTS.

Disclaimer

The DEKRA True View Inspection is a visual and functional check of listed items. Concealed/hidden defects are not covered. DEKRA does not dismantle or strip parts. Road testing is limited. Valid only for the vehicle and condition at inspection time. DEKRA T&Cs apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave, Klerksoord, Pretoria, 0200
Phone: 012 542 4867 | www.dekraauto.co.za

VIN: JTDJWCA3S00A56757