DEKRA

True View Inspection

Report No: 2017327098
Date: 18/11/2026



Assignment

Requested Date:	18/11/2026	**Inspection Location:**	DEKRA Newton Park 56 7th AVE CORNER FRANK STREET NEWTON PARK - 6001 NEWTON PARK - EC
Inspection Date:	18/11/2026		

Vehicle Data

Vehicle Type:	PASSENGER VEHICLE	**Reg No:**	MS02LNGP
Manufacturer:	VOLKSWAGEN	**Register No:**	KJN993K
Model:	POLO VIVO 1.6 LIFE 5-DR TIPTRONIC [2025-ON]	**First Licensing:**	
		Fuel:	PETROL
VIN:	AAVZZZ6R2TU003993	**Odometer:**	17,816 KM
Engine No:	CLS876277		

Exhaust System

Brakes

Axle	Left Braking Force [KN]	Right Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.2	2.2	-	
Rear	1.4	1.3	-	
Emergency / Parking	1.2	0.9	-	

Tyres

Position	Size	Load/Speed Index	Manufacturer	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185 60 R15	84 H	Continantal	Conti	V	3325	4
Front Right	185 60 R15	84 H	Continantal	Conti	V	3325	4
Rear Left	185 60 R15	84 H	Continantal	Conti	V	3325	6
Rear Right	185 60 R15	84 H	Continantal	Conti	V	3325	6
Spare	175 70 R14	84 T	Giticomfort	Giti	V	2024	8

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufactures).

Axles & Undercarriage

Electrical Systems

Engine & Transmission

Exterior & Interior

General Photos



1. Front right corner



2. Rear left corner



3. Interior (Front driver door)



4. Dashboard (Taken from the rear seat)



5. Cluster (While engine is running)



6. Odometer



7. License disc



8. VIN plate/sticker



9. Front



10. Right



11. Rear



12. Left



13. Front left tyre tread



14. Rear left tyre tread



15. Rear right tyre tread



16. Front right tyre tread



17. Engine compartment



18. Oil cap and dip stick



19. Expansion bottle/Coolant level



20. Engine bottom



21. Chassis front



22. Chassis rear

Inspection Conditions

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

General Comments

ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE EXTERIOR AND INTERIOR ELECTRICAL AND MECHANICAL PARTS.

Disclaimer

The DEKRA True View Inspection is a visual and functional check of listed items. Concealed/hidden defects are not covered. DEKRA does not dismantle or strip parts. Road testing is limited. Valid only for the vehicle and condition at inspection time. DEKRA T&Cs apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave, Klerksoord, Pretoria, 0200
Phone: 012 542 4867 | www.dekraauto.co.za

VIN: AAVZZZ6R2TU003993