True View Inspection

Report No: 2017315903
Date: 22/10/2026



Assignment

Requested Date:	22/10/2026	**Inspection Location:**	DEKRA EGOLI 103 turffontein road turffontein - 2190 EGOLI - GT
Inspection Date:	22/10/2026		

Vehicle Data

Vehicle Type:	PASSENGER VEHICLE	**Reg No:**	MV09NFGP
Manufacturer:	VOLKSWAGEN	**Register No:**	KJX260K
Model:	POLO VIVO 1.6 LIFE 5-DR TIPTRONIC [2025-ON]	**First Licensing:**	
		Fuel:	PETROL
VIN:	AAVZZZ6R9TU006261	**Odometer:**	10,815 KM
Engine No:	CLS876897		

Exhaust System

Brakes

Axle	Left Braking Force [KN]	Right Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	1.8	1.7	-	
Rear	0.9	1.0	-	
Emergency / Parking	0.8	1	-	

Tyres

Position	Size	Load/Speed Index	Manufacturer	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/60R15	84H	Continental	Contipremium	V	3625	5
Front Right	185/60R15	84H	Continental	Contipremium	V	3625	5
Rear Left	185/60R15	84H	Continental	Contipremium	V	3625	6
Rear Right	185/60R15	84H	Continental	Contipremium	V	3625	6
Spare	175/70R14	84T	Giti	Giti comfort	V	0000	6

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufactures).

Axles & Undercarriage

Electrical Systems

Engine & Transmission

Exterior & Interior



Aerial: Rear Centre - Missing.



Door: Rear Left - Residual Traces of Repair.



Fender: Rear Left - Residual Traces of Repair.

Inspection Conditions

Engine number not visible without dismantling. Inspection conditions were sufficient.

Engine number â€“ not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

General Comments

ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE: NORMAL WEAR AND TEAR MARKS ON THE BODY, INTERIOR AND MECHANICAL. TRACES OF RESPRAY AND REPAIR WORK ON SOME BODY PANELS.

Disclaimer

The DEKRA True View Inspection is a visual and functional check of listed items. Concealed/hidden defects are not covered. DEKRA does not dismantle or strip parts. Road testing is limited. Valid only for the vehicle and condition at inspection time. DEKRA T&Cs apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave, Klerksoord, Pretoria, 0200
Phone: 012 542 4867 | www.dekraauto.co.za

VIN: AAVZZZ6R9TU006261